




LOW COUNTRY LINE


borden partnership llp
gordon county, georgia





historical mapping of north georgia 1794-1898

T E N N E S S E E




9°E (2006 16)

84°

9°E (2006 17)

10


NORTH CAROLINA








southern typologies: dogtrot + shotgun




regional climate maps


Map of Wind Speed
at April 25, 2006 1300 EST




KBDI Deviation from Normal
at April 25, 2006 1300 EST




Map of Temperature
at April 25, 2006 1300 EST




Forecast Fire Danger for Tomorrow
Produced at April 25, 2006 130pm EST



From Viasala through BLM
For the last 24 hours. Ending Time: April 21, 2006



And Wind Direction
at April 25, 2006 1300 EST




Map of 10-Hour Fuel Moisture
at April 25, 2006 1300 EST




Map of Last 24 Hour Rainfall
at April 26, 2006 0600 EST





Fire Danger Rating
as of April 25, 2006 230pm




Map of KBDI
at April 25, 2006 1300 EST




Map of Relative Humidity
at April 25, 2006 1300 EST







HOUSE AS FURNITURE




LIGHT




GENERAL HEATING - SPECIFIC HEATING




ENCLOSURE



WATER



GROUND




FIXED ENCLOSURE - VARIABLE ENCLOSURE


conceptual diagrams

PIERS


WIND - DOGTROT




HOUSE TO CAR



HOUSE TO YARD




GUEST



NORTH




WIND







ORIENTATION



roof plan














longitudinal elevation


20







guest



dogtrot porch



fireboxes




louvers




exterior rooms



galleries




operable skin



sleep zones



service cores






trombe walls














view of guest porch







dogtrot entry






longitudinal elevation






aerial view







view along length







operable panel wall






living room





aerial view






carport + service entry







porch face






gallery






entry axis





longitudinal section






longitudinal section






section through master






section through gallery








section through living room







section through dogtrot porch





section through guest quarters





central dividing doortrot proch